

REBOUL, MACMURRAY, HEWITT, MAYNARD & KRISTOL

45 ROCKEFELLER PLAZA

NEW YORK, N. Y. 10111

WILLIAM J. HEWITT  
HOWARD G. KRISTOL  
JOHN C. MACMURRAY  
JOHN MAYNARD  
JOHN W. REBOUL  
WAYNE A. CROSS  
WILLIAM F. MCCORMACK  
ROBERT SCHEFF  
ROBERT A. SCHWED  
DAVID S. ELKIND  
CHARLES D. UNIMAN  
ROBERT P. DEVLIN  
JAMES E. MAGEE (D.C. BAR)  
ROBERT L. SILLS  
CHARLES W. SPRAGUE  
WILLIAM I. SUSSMAN  
MARK J. TANNENBAUM  
ANDREW P. TASHMAN  
ROBERT M. PEAK  
ROBERT COULTAS  
EDWARD A. McDONALD

1-304A020

TELEPHONE: (212) 841-5700  
TELECOPIER: (212) 841-5725

SUITE 728  
523 WEST SIXTH STREET  
LOS ANGELES, CALIF. 90014  
TELEPHONE: (213) 612-0822  
TELECOPIER: (213) 895-0108

SUITE 406  
1111 NINETEENTH STREET, N. W.  
WASHINGTON, D. C. 20036  
TELEPHONE: (202) 429-0004  
TELECOPIER: (202) 429-8743

MICHAEL DOWNEY RICE  
COUNSEL

October 30, 1991

17576

RECORDATION NO \_\_\_\_\_ FILED 1425

OCT 31 1991 - 11 52 AM

INTERSTATE COMMERCE COMMISSION

17576

RECORDATION NO \_\_\_\_\_ FILED 1425

OCT 31 1991 - 11 52 AM

INTERSTATE COMMERCE COMMISSION

Mr. Sidney L. Strickland, Jr.  
Secretary  
Interstate Commerce Commission  
Washington, DC 20423

17576-B

RECORDATION NO \_\_\_\_\_ FILED 1425

OCT 31 1991 - 11 52 AM

INTERSTATE COMMERCE COMMISSION

Dear Secretary:

Enclosed are counterparts of the documents described below, to be recorded pursuant to Section 11303 of Title 49 of the U.S. Code:

Lease Agreement dated as of October 15, 1991, a primary document.

Indenture, Mortgage and Security Agreement dated as of October 15, 1991, a primary document.

Lease and Indenture Supplement dated as of October 31, 1991, a secondary document.

The names and addresses of the parties to the documents are as follows:

Lessee: CSX Transportation, Inc.  
100 North Charles Street  
Baltimore, Maryland 21201

Owner Trustee and Lessor: First Security Bank of Utah, National Association  
79 South Main Street  
Salt Lake City, Utah 84130

Indenture Trustee:

Mercantile-Safe Deposit and Trust Company  
Two Hopkins Plaza  
Baltimore, Maryland 21201

The equipment covered by the documents consists of 3,400 100-ton bathtub gondola cars bearing the road numbers of CSX Transportation, Inc. listed on the schedule attached hereto. ✓

A short summary of the documents to appear in the index is as follows:

Lease Agreement dated as of October 15, 1991, between First Security Bank of Utah, National Association, as owner trustee, as lessor, and CSX Transportation, Inc., as lessee

Indenture, Mortgage and Security Agreement dated as of October 15, 1991, among First Security Bank of Utah, National Association, not in its individual capacity but as owner trustee, Mercantile-Safe Deposit and Trust Company, as indenture trustee, and CSX Transportation, Inc., as lessee.

Lease and Indenture Supplement No. 1 dated as of October 31, 1991, among First Security Bank of Utah, National Association, not in its individual capacity but solely as owner trustee, CSX Transportation, Inc., as lessee, and Mercantile-Safe Deposit and Trust Company, not in its individual capacity but solely as indenture trustee

A fee of \$15.00 is enclosed. Please return any extra copies not needed by the Commission for recordation to James E. Magee of this firm at 1111 19th Street, N.W., Washington, D.C. 20036.

Very truly yours,

  
Jay S. Rand

Enclosures

17576 B  
RECORDATION NO. FILED

LEASE AND INDENTURE SUPPLEMENT NO. 1

OCT 31 1991 11 52 AM

Dated October 31, 1991

INTERSTATE COMMERCE COMMISSION

Among

FIRST SECURITY BANK OF UTAH, NATIONAL ASSOCIATION  
not in its individual capacity but solely as trustee,  
Lessor/Owner Trustee,

CSX TRANSPORTATION, INC.,  
Lessee

and

MERCANTILE-SAFE DEPOSIT AND TRUST COMPANY  
not in its individual capacity but solely as trustee,  
Indenture Trustee

3400 100-Ton Bathtub Gondola Cars

---

CERTAIN RIGHTS, TITLE AND INTEREST IN AND TO THIS LEASE AND  
INDENTURE SUPPLEMENT NO. 1 AND TO THE UNITS COVERED HEREBY ON THE  
PART OF FIRST SECURITY BANK OF UTAH, NATIONAL ASSOCIATION, AS  
OWNER TRUSTEE, HAVE BEEN ASSIGNED TO AND ARE SUBJECT TO A LIEN  
AND SECURITY INTEREST IN FAVOR OF MERCANTILE-SAFE DEPOSIT AND  
TRUST COMPANY, AS INDENTURE TRUSTEE UNDER AN INDENTURE, MORTGAGE  
AND SECURITY AGREEMENT DATED AS OF OCTOBER 15, 1991. NO SECURITY  
INTEREST IN THIS LEASE AND INDENTURE SUPPLEMENT NO. 1 MAY BE  
CREATED THROUGH THE TRANSFER OR POSSESSION OF ANY COUNTERPART  
OTHER THAN THE ORIGINAL COUNTERPART. THIS IS NOT THE ORIGINAL.

---

FILED WITH THE INTERSTATE COMMERCE COMMISSION PURSUANT  
TO 49 U.S.C. § 11303 ON OCTOBER \_\_\_\_, 1991 at \_\_\_\_:\_\_\_\_.M.,  
RECORDATION NUMBER \_\_\_\_ AND DEPOSITED WITH THE OFFICE  
OF THE REGISTRAR GENERAL OF CANADA PURSUANT TO  
§ 90 OF THE RAILWAY ACT OF CANADA ON OCTOBER \_\_\_\_, 1991  
AT \_\_\_\_:\_\_\_\_.M., RECORDATION NUMBER \_\_\_\_.

THIS LEASE AND INDENTURE SUPPLEMENT NO. 1, dated October 31, 1991, among FIRST SECURITY BANK OF UTAH, NATIONAL ASSOCIATION, a national banking association, not in its individual capacity but solely as Owner Trustee ("Lessor" or "Owner Trustee") under that certain Trust Agreement dated as of August 1, 1991 (the "Trust Agreement"), with CSX Intermodal, Inc., CSX TRANSPORTATION, INC., a Virginia corporation ("Lessee") and MERCANTILE-SAFE DEPOSIT AND TRUST COMPANY, a Maryland trust company, not in its individual capacity but solely as Indenture Trustee (the "Indenture Trustee").

W I T N E S S E T H:

WHEREAS, Lessor, Lessee and the Indenture Trustee have, with the Owner Participant referred to therein, heretofore entered into a Participation Agreement (the "Participation Agreement"), Lessor and Lessee have heretofore entered into a Lease Agreement (the "Lease"), and the Indenture Trustee, the Owner Trustee, and the Lessee have heretofore entered into an Indenture, Mortgage and Security Agreement (the "Indenture"), each dated as of October 15, 1991 (capitalized terms used herein without definitions having the respective meanings set forth in Schedule X to the Lease);

WHEREAS, the Participation Agreement and the Lease provide that on the Closing Date Seller shall deliver to Owner Trustee a Bill of Sale dated such date by which Seller bargains, conveys, assigns, sets over, sells and delivers to Owner Trustee, and Owner Trustee purchases and accepts from the Seller, the Units to be conveyed on such Closing Date, and said Bill of Sale has been delivered by Seller and accepted by Owner Trustee on the Closing Date; and

WHEREAS, the Participation Agreement, the Lease, and the Indenture provide for the execution of a Lease and Indenture Supplement substantially in the form hereof for the purposes of leasing the Units under the Lease as and when delivered by Lessor to Lessee in accordance with the terms thereof and subjecting such Units to the Lien of the Indenture;

NOW, THEREFORE, in consideration of the premises and for good and sufficient consideration, Lessor, Lessee and Indenture Trustee hereby agree as follows:

a. Lessor hereby delivers and leases to Lessee, and Lessee hereby accepts and leases from Lessor, under the Lease as hereby supplemented, the Units listed on Schedule 1 hereto.

b. Lessee hereby confirms to Lessor that Lessee has accepted such Units for all purposes hereof and of the Lease. The date of delivery and acceptance of such Units under the Lease is the date of this Lease and Indenture Supplement No. 1 set

forth in the opening paragraph hereof. The Lease Term for such Units shall commence on the date hereof.

c. The aggregate Lessor's Cost of the Units leased hereunder is \$116,960,000 and the amounts comprising such Lessor's Cost and the Lessor's Cost of each Unit leased hereunder are set forth on Schedule 1 hereto. The Basic Rent, Stipulated Loss Values and Termination Values for the Units set forth, respectively, on Schedules 2, 3 and 4 hereto shall be applicable in respect of the Units leased hereunder on the date hereof.

d. Lessee hereby confirms its agreement, in accordance with the Lease as supplemented by this Lease and Indenture Supplement No. 1, on the Basic Term Commencement Date to pay Interim Rent to Lessor for each Unit leased hereunder as provided for in the Lease and on each Payment Date to pay Basic Rent to Lessor for each Unit leased hereunder as provided for in the Lease.

e. In order to secure the prompt payment of the principal of and Premium, if any, and interest on all of the Certificates from time to time Outstanding under the Indenture and of all other amounts payable to or for the benefit of the Holders of the Certificates and the Indenture Trustee under the Indenture, the Participation Agreement and the Indenture Estate Documents, and the performance and observance by the Owner Participant and the Owner Trustee of all agreements, covenants and provisions contained in the Indenture or in any other Operative Document, Lessor has granted, conveyed, pledged, sold, mortgaged, assigned, transferred and set over a security interest unto the Indenture Trustee in (i) the Units listed on Schedule 1 hereto and (ii) this Lease and Indenture Supplement No. 1, in each case excluding Excepted Property and Excepted Rights, to have and to hold unto the Indenture Trustee and its successors and its assigns in trust for the benefit and security for the Holders from time to time of the Certificates and for its and their own use and benefit forever.

f. All of the provisions of the Lease and the Indenture are hereby incorporated by reference in this Lease and Indenture Supplement No. 1 to the same extent as if fully set forth herein.

g. This Lease and Indenture Supplement No. 1 may be executed by the parties hereto in separate counterparts, each of which when so executed and delivered shall be an original, but all such counterparts shall together constitute but one and the same instrument.

h. This Lease and Indenture Supplement No. 1 is being delivered in the State of Utah and shall in all respects be governed by, and construed in accordance with, the laws of the

State of Utah, including all matters of construction, validity and performance.

IN WITNESS WHEREOF, Lessor, Lessee and Indenture Trustee have caused this Lease and Indenture Supplement No. 1 to be duly executed on the date and year set forth in the opening paragraph hereof.

Lessor/Owner Trustee

FIRST SECURITY BANK OF UTAH,  
NATIONAL ASSOCIATION  
not in its individual  
capacity but solely as  
Owner Trustee

By Val J. Ostr  
Title: ASSISTANT VICE PRESIDENT

Lessee

CSX TRANSPORTATION, INC.

By Michael J. Martino  
Title: ASSISTANT TREASURER

Indenture Trustee

MERCANTILE-SAFE DEPOSIT AND  
TRUST COMPANY  
not in its individual  
capacity but solely as  
Indenture Trustee

By [Signature]  
Title: VICE PRESIDENT

Attest: Robert D. Brown  
Corporate Trust Officer


STATE OF UTAH )  
 ) ss.:  
COUNTY OF SALT LAKE )

On this 29th day of October, before me personally appeared WALT ORTON, to be personally known, who, being by me duly sworn, says that he/she is ASSISTANT VICE PRESIDENT of First Security Bank of Utah, National Association, that said instrument was signed and sealed on behalf of said corporation by authority of its Board of Directors and he/she acknowledged that the execution of the foregoing instrument was the free act and deed of said corporation.

*Lisa N. Brayton*  
\_\_\_\_\_  
Notary Public

My Commission Expires: **SEP 5 1995**

[Notary Seal]



STATE OF MARYLAND     )  
                                  :    ss.:  
CITY OF BALTIMORE    )

On this <sup>*Asst.*</sup> 30th day of October, 1991, before me personally appeared Michael J. Mortens to be personally known, who, being by me duly sworn, says that he is Treasurer of CSX Transportation, Inc., that said instrument was signed and sealed on behalf of said corporation by authority of its Board of Directors and he acknowledged that the execution of the foregoing instrument was the free act and deed of said corporation.

*Karen Luebelusen*  
\_\_\_\_\_  
Notary Public

My Commission Expires: *10/1/93*

[Notary Seal]



STATE OF MARYLAND        )  
                                  : ss.:  
COUNTY OF BALTIMORE    )

On this 30th day of October, 1991, before me personally appeared John M. Mitchell, to be personally known, who, being by me duly sworn, says that he is Vice President of Mercantile-Safe Deposit and Trust Company, that said instrument was signed and sealed on behalf of said trust company by authority of its Board of Directors and he acknowledged that the execution of the foregoing instrument was the free act and deed of said trust company.

Karen Luebeckson  
Notary Public

My Commission Expires: 10/1/93  
[Notary Public]



SCHEDULE OF UNITS TO BE DELIVERED

<u>Quantity</u>	<u>Type</u>	<u>CSXT Road Numbers</u>	<u>Lessor's Cost Per Unit</u>	<u>Aggregate Lessor's Cost</u>
3400	100-ton bathtub gondola cars	(See attached Schedule)	\$34,400	\$116,960,000

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385310
CSXT	385311
CSXT	385312
CSXT	385313
CSXT	385314
CSXT	385315
CSXT	385316
CSXT	385317
CSXT	385318
CSXT	385319
CSXT	385320
CSXT	385321
CSXT	385322
CSXT	385323
CSXT	385324
CSXT	385325
CSXT	385326
CSXT	385327
CSXT	385328
CSXT	385329
CSXT	385330
CSXT	385331
CSXT	385332
CSXT	385333
CSXT	385334
CSXT	385335
CSXT	385336
CSXT	385337
CSXT	385338
CSXT	385339
CSXT	385340
CSXT	385341
CSXT	385342
CSXT	385343
CSXT	385344
CSXT	385345
CSXT	385346
CSXT	385347
CSXT	385348
CSXT	385349
CSXT	385350
CSXT	385351
CSXT	385352
CSXT	385353
CSXT	385354
CSXT	385355
CSXT	385356
CSXT	385357
CSXT	385358
CSXT	385359
CSXT	385360
CSXT	385361
CSXT	385362
CSXT	385363
CSXT	385364
CSXT	385365
CSXT	385366

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385367
CSXT	385368
CSXT	385369
CSXT	385370
CSXT	385371
CSXT	385372
CSXT	385373
CSXT	385374
CSXT	385375
CSXT	385376
CSXT	385377
CSXT	385378
CSXT	385379
CSXT	385380
CSXT	385381
CSXT	385382
CSXT	385383
CSXT	385384
CSXT	385385
CSXT	385386
CSXT	385387
CSXT	385388
CSXT	385389
CSXT	385390
CSXT	385391
CSXT	385392
CSXT	385393
CSXT	385394
CSXT	385395
CSXT	385396
CSXT	385397
CSXT	385398
CSXT	385399
CSXT	385400
CSXT	385401
CSXT	385402
CSXT	385403
CSXT	385404
CSXT	385405
CSXT	385406
CSXT	385407
CSXT	385408
CSXT	385409
CSXT	385410
CSXT	385411
CSXT	385412
CSXT	385413
CSXT	385414
CSXT	385415
CSXT	385416
CSXT	385417
CSXT	385418
CSXT	385419
CSXT	385420
CSXT	385421
CSXT	385422
CSXT	385423

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385424
CSXT	385425
CSXT	385426
CSXT	385427
CSXT	385428
CSXT	385429
CSXT	385430
CSXT	385431
CSXT	385432
CSXT	385433
CSXT	385434
CSXT	385435
CSXT	385436
CSXT	385437
CSXT	385438
CSXT	385439
CSXT	385440
CSXT	385441
CSXT	385442
CSXT	385443
CSXT	385444
CSXT	385445
CSXT	385446
CSXT	385447
CSXT	385448
CSXT	385449
CSXT	385450
CSXT	385451
CSXT	385452
CSXT	385453
CSXT	385454
CSXT	385455
CSXT	385456
CSXT	385457
CSXT	385458
CSXT	385459
CSXT	385460
CSXT	385461
CSXT	385462
CSXT	385463
CSXT	385464
CSXT	385465
CSXT	385466
CSXT	385467
CSXT	385468
CSXT	385469
CSXT	385470
CSXT	385471
CSXT	385472
CSXT	385473
CSXT	385474
CSXT	385475
CSXT	385476
CSXT	385477
CSXT	385478
CSXT	385479
CSXT	385480

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	385481
CSXT	385482
CSXT	385483
CSXT	385484
CSXT	385485
CSXT	385486
CSXT	385487
CSXT	385488
CSXT	385489
CSXT	385490
CSXT	385491
CSXT	385492
CSXT	385493
CSXT	385494
CSXT	385495
CSXT	385496
CSXT	385497
CSXT	385498
CSXT	385499
CSXT	385500
CSXT	385501
CSXT	385502
CSXT	385503
CSXT	385504
CSXT	385505
CSXT	385506
CSXT	385507
CSXT	385508
CSXT	385509
CSXT	385510
CSXT	385511
CSXT	385512
CSXT	385513
CSXT	385514
CSXT	385515
CSXT	385516
CSXT	385517
CSXT	385518
CSXT	385519
CSXT	385520
CSXT	385521
CSXT	385522
CSXT	385523
CSXT	385524
CSXT	385525
CSXT	385526
CSXT	385527
CSXT	385528
CSXT	385529
CSXT	385530
CSXT	385531
CSXT	385532
CSXT	385533
CSXT	385534
CSXT	385535
CSXT	385536
CSXT	385537

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385538
CSXT	385539
CSXT	385540
CSXT	385541
CSXT	385542
CSXT	385543
CSXT	385544
CSXT	385545
CSXT	385546
CSXT	385547
CSXT	385548
CSXT	385549
CSXT	385550
CSXT	385551
CSXT	385552
CSXT	385553
CSXT	385554
CSXT	385555
CSXT	385556
CSXT	385557
CSXT	385558
CSXT	385559
CSXT	385560
CSXT	385561
CSXT	385562
CSXT	385563
CSXT	385564
CSXT	385565
CSXT	385566
CSXT	385567
CSXT	385568
CSXT	385569
CSXT	385570
CSXT	385571
CSXT	385572
CSXT	385573
CSXT	385574
CSXT	385575
CSXT	385576
CSXT	385577
CSXT	385578
CSXT	385579
CSXT	385580
CSXT	385581
CSXT	385582
CSXT	385583
CSXT	385584
CSXT	385585
CSXT	385586
CSXT	385587
CSXT	385588
CSXT	385589
CSXT	385590
CSXT	385591
CSXT	385592
CSXT	385593
CSXT	385594

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385595
CSXT	385596
CSXT	385597
CSXT	385598
CSXT	385599
CSXT	385600
CSXT	385601
CSXT	385602
CSXT	385603
CSXT	385604
CSXT	385605
CSXT	385606
CSXT	385607
CSXT	385608
CSXT	385609
CSXT	385610
CSXT	385611
CSXT	385612
CSXT	385613
CSXT	385614
CSXT	385615
CSXT	385616
CSXT	385617
CSXT	385618
CSXT	385619
CSXT	385620
CSXT	385621
CSXT	385622
CSXT	385623
CSXT	385624
CSXT	385625
CSXT	385626
CSXT	385627
CSXT	385628
CSXT	385629
CSXT	385630
CSXT	385631
CSXT	385632
CSXT	385633
CSXT	385634
CSXT	385635
CSXT	385636
CSXT	385637
CSXT	385638
CSXT	385639
CSXT	385640
CSXT	385641
CSXT	385642
CSXT	385643
CSXT	385644
CSXT	385645
CSXT	385646
CSXT	385647
CSXT	385648
CSXT	385649
CSXT	385650
CSXT	385651

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385652
CSXT	385653
CSXT	385654
CSXT	385655
CSXT	385656
CSXT	385657
CSXT	385658
CSXT	385659
CSXT	385660
CSXT	385661
CSXT	385662
CSXT	385663
CSXT	385664
CSXT	385665
CSXT	385666
CSXT	385667
CSXT	385668
CSXT	385669
CSXT	385670
CSXT	385671
CSXT	385672
CSXT	385673
CSXT	385674
CSXT	385675
CSXT	385676
CSXT	385677
CSXT	385678
CSXT	385679
CSXT	385680
CSXT	385681
CSXT	385682
CSXT	385683
CSXT	385684
CSXT	385685
CSXT	385686
CSXT	385687
CSXT	385688
CSXT	385689
CSXT	385690
CSXT	385691
CSXT	385692
CSXT	385693
CSXT	385694
CSXT	385695
CSXT	385696
CSXT	385697
CSXT	385698
CSXT	385699
CSXT	385700
CSXT	385701
CSXT	385702
CSXT	385703
CSXT	385704
CSXT	385705
CSXT	385706
CSXT	385707
CSXT	385708

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385709
CSXT	385710
CSXT	385711
CSXT	385712
CSXT	385713
CSXT	385714
CSXT	385715
CSXT	385716
CSXT	385717
CSXT	385718
CSXT	385719
CSXT	385720
CSXT	385721
CSXT	385722
CSXT	385723
CSXT	385724
CSXT	385725
CSXT	385726
CSXT	385727
CSXT	385728
CSXT	385729
CSXT	385730
CSXT	385731
CSXT	385732
CSXT	385733
CSXT	385734
CSXT	385735
CSXT	385736
CSXT	385737
CSXT	385738
CSXT	385739
CSXT	385740
CSXT	385741
CSXT	385742
CSXT	385743
CSXT	385744
CSXT	385745
CSXT	385746
CSXT	385747
CSXT	385748
CSXT	385749
CSXT	385750
CSXT	385751
CSXT	385752
CSXT	385753
CSXT	385754
CSXT	385755
CSXT	385756
CSXT	385757
CSXT	385758
CSXT	385759
CSXT	385760
CSXT	385761
CSXT	385762
CSXT	385763
CSXT	385764
CSXT	385765

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385766
CSXT	385767
CSXT	385768
CSXT	385769
CSXT	385770
CSXT	385771
CSXT	385772
CSXT	385773
CSXT	385774
CSXT	385775
CSXT	385776
CSXT	385777
CSXT	385778
CSXT	385779
CSXT	385780
CSXT	385781
CSXT	385782
CSXT	385783
CSXT	385784
CSXT	385785
CSXT	385786
CSXT	385787
CSXT	385788
CSXT	385789
CSXT	385790
CSXT	385791
CSXT	385792
CSXT	385793
CSXT	385794
CSXT	385795
CSXT	385796
CSXT	385797
CSXT	385798
CSXT	385799
CSXT	385800
CSXT	385801
CSXT	385802
CSXT	385803
CSXT	385804
CSXT	385805
CSXT	385806
CSXT	385807
CSXT	385808
CSXT	385809
CSXT	385810
CSXT	385811
CSXT	385812
CSXT	385813
CSXT	385814
CSXT	385815
CSXT	385816
CSXT	385817
CSXT	385818
CSXT	385819
CSXT	385820
CSXT	385821
CSXT	385822

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	385823
CSXT	385824
CSXT	385825
CSXT	385826
CSXT	385827
CSXT	385828
CSXT	385829
CSXT	385830
CSXT	385831
CSXT	385832
CSXT	385833
CSXT	385834
CSXT	385835
CSXT	385836
CSXT	385837
CSXT	385838
CSXT	385839
CSXT	385840
CSXT	385841
CSXT	385842
CSXT	385843
CSXT	385844
CSXT	385845
CSXT	385846
CSXT	385847
CSXT	385848
CSXT	385849
CSXT	385850
CSXT	385851
CSXT	385852
CSXT	385853
CSXT	385854
CSXT	385855
CSXT	385856
CSXT	385857
CSXT	385858
CSXT	385859
CSXT	385860
CSXT	385861
CSXT	385862
CSXT	385863
CSXT	385864
CSXT	385865
CSXT	385866
CSXT	385867
CSXT	385868
CSXT	385869
CSXT	385870
CSXT	385871
CSXT	385872
CSXT	385873
CSXT	385874
CSXT	385875
CSXT	385876
CSXT	385877
CSXT	385878
CSXT	385879

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385880
CSXT	385881
CSXT	385882
CSXT	385883
CSXT	385884
CSXT	385885
CSXT	385886
CSXT	385887
CSXT	385888
CSXT	385889
CSXT	385890
CSXT	385891
CSXT	385892
CSXT	385893
CSXT	385894
CSXT	385895
CSXT	385896
CSXT	385897
CSXT	385898
CSXT	385899
CSXT	385900
CSXT	385901
CSXT	385902
CSXT	385903
CSXT	385904
CSXT	385905
CSXT	385906
CSXT	385907
CSXT	385908
CSXT	385909
CSXT	385910
CSXT	385911
CSXT	385912
CSXT	385913
CSXT	385914
CSXT	385915
CSXT	385916
CSXT	385917
CSXT	385918
CSXT	385919
CSXT	385920
CSXT	385921
CSXT	385922
CSXT	385923
CSXT	385924
CSXT	385925
CSXT	385926
CSXT	385927
CSXT	385928
CSXT	385929
CSXT	385930
CSXT	385931
CSXT	385932
CSXT	385933
CSXT	385934
CSXT	385935
CSXT	385936

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	385937
CSXT	385938
CSXT	385939
CSXT	385940
CSXT	385941
CSXT	385942
CSXT	385943
CSXT	385944
CSXT	385945
CSXT	385946
CSXT	385947
CSXT	385948
CSXT	385949
CSXT	385950
CSXT	385951
CSXT	385952
CSXT	385953
CSXT	385954
CSXT	385955
CSXT	385956
CSXT	385957
CSXT	385958
CSXT	385959
CSXT	385960
CSXT	385961
CSXT	385962
CSXT	385963
CSXT	385964
CSXT	385965
CSXT	385966
CSXT	385967
CSXT	385968
CSXT	385969
CSXT	385970
CSXT	385971
CSXT	385972
CSXT	385973
CSXT	385974
CSXT	385975
CSXT	385976
CSXT	385977
CSXT	385978
CSXT	385979
CSXT	385980
CSXT	385981
CSXT	385982
CSXT	385983
CSXT	385984
CSXT	385985
CSXT	385986
CSXT	385987
CSXT	385988
CSXT	385989
CSXT	385990
CSXT	385991
CSXT	385992
CSXT	385993

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	386165
CSXT	386166
CSXT	386167
CSXT	386168
CSXT	386169
CSXT	386170
CSXT	386171
CSXT	386172
CSXT	386173
CSXT	386174
CSXT	386175
CSXT	386176
CSXT	386177
CSXT	386178
CSXT	386179
CSXT	386180
CSXT	386181
CSXT	386182
CSXT	386183
CSXT	386184
CSXT	386185
CSXT	386186
CSXT	386187
CSXT	386188
CSXT	386189
CSXT	386190
CSXT	386191
CSXT	386192
CSXT	386193
CSXT	386194
CSXT	386195
CSXT	386196
CSXT	386197
CSXT	386198
CSXT	386199
CSXT	386200
CSXT	386201
CSXT	386202
CSXT	386203
CSXT	386204
CSXT	386205
CSXT	386206
CSXT	386207
CSXT	386208
CSXT	386209
CSXT	386210
CSXT	386211
CSXT	386212
CSXT	386213
CSXT	386214
CSXT	386215
CSXT	386216
CSXT	386217
CSXT	386218
CSXT	386219
CSXT	386220
CSXT	386221

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	386222
CSXT	386223
CSXT	386224
CSXT	386225
CSXT	386226
CSXT	386227
CSXT	386228
CSXT	386229
CSXT	386230
CSXT	386231
CSXT	386232
CSXT	386233
CSXT	386234
CSXT	386235
CSXT	386236
CSXT	386237
CSXT	386238
CSXT	386239
CSXT	386240
CSXT	386241
CSXT	386242
CSXT	386243
CSXT	386244
CSXT	386245
CSXT	386246
CSXT	386247
CSXT	386248
CSXT	386249
CSXT	386250
CSXT	386251
CSXT	386252
CSXT	386253
CSXT	386254
CSXT	386255
CSXT	386256
CSXT	386257
CSXT	386258
CSXT	386259
CSXT	386260
CSXT	386261
CSXT	386262
CSXT	386263
CSXT	386264
CSXT	386265
CSXT	386266
CSXT	386267
CSXT	386268
CSXT	386269
CSXT	386270
CSXT	386271
CSXT	386272
CSXT	386273
CSXT	386274
CSXT	386275
CSXT	386276
CSXT	386277
CSXT	386278

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	386279
CSXT	386280
CSXT	386281
CSXT	386282
CSXT	386283
CSXT	386284
CSXT	386285
CSXT	386286
CSXT	386287
CSXT	386288
CSXT	386289
CSXT	386290
CSXT	386291
CSXT	386292
CSXT	386293
CSXT	386294
CSXT	386295
CSXT	386296
CSXT	386297
CSXT	386298
CSXT	386299
CSXT	386300
CSXT	386301
CSXT	386302
CSXT	386303
CSXT	386304
CSXT	386305
CSXT	386306
CSXT	386307
CSXT	386308
CSXT	386309
CSXT	386310
CSXT	386311
CSXT	386312
CSXT	386313
CSXT	386314
CSXT	386315
CSXT	386316
CSXT	386317
CSXT	386318
CSXT	386319
CSXT	386320
CSXT	386321
CSXT	386322
CSXT	386323
CSXT	386324
CSXT	386325
CSXT	386326
CSXT	386327
CSXT	386328
CSXT	386329
CSXT	386330
CSXT	386331
CSXT	386332
CSXT	386333
CSXT	386334
CSXT	386335

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	386336
CSXT	386337
CSXT	386338
CSXT	386339
CSXT	386340
CSXT	386341
CSXT	386342
CSXT	386343
CSXT	386344
CSXT	386345
CSXT	386346
CSXT	386347
CSXT	386348
CSXT	386349
CSXT	386350
CSXT	386351
CSXT	386352
CSXT	386353
CSXT	386354
CSXT	386355
CSXT	386356
CSXT	386357
CSXT	386358
CSXT	386359
CSXT	386360
CSXT	386361
CSXT	386362
CSXT	386363
CSXT	386364
CSXT	386365
CSXT	386366
CSXT	386367
CSXT	386368
CSXT	386369
CSXT	386370
CSXT	386371
CSXT	386372
CSXT	386373
CSXT	386374
CSXT	386375
CSXT	386376
CSXT	386377
CSXT	386378
CSXT	386379
CSXT	386380
CSXT	386381
CSXT	386382
CSXT	386383
CSXT	386384
CSXT	386385
CSXT	386386
CSXT	386387
CSXT	386388
CSXT	386389
CSXT	386390
CSXT	386391
CSXT	386392

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	386393
CSXT	386394
CSXT	386395
CSXT	386396
CSXT	386397
CSXT	386398
CSXT	386399
CSXT	386400
CSXT	386401
CSXT	386402
CSXT	386403
CSXT	386404
CSXT	386405
CSXT	386406
CSXT	386407
CSXT	386408
CSXT	386409
CSXT	386410
CSXT	386411
CSXT	386412
CSXT	386413
CSXT	386414
CSXT	386415
CSXT	386416
CSXT	386417
CSXT	386418
CSXT	386419
CSXT	386420
CSXT	386421
CSXT	386422
CSXT	386423
CSXT	386424
CSXT	386425
CSXT	386426
CSXT	386427
CSXT	386428
CSXT	386429
CSXT	386430
CSXT	386431
CSXT	386432
CSXT	386433
CSXT	386434
CSXT	386435
CSXT	386436
CSXT	386437
CSXT	386438
CSXT	386439
CSXT	386440
CSXT	386441
CSXT	386442
CSXT	386443
CSXT	386444
CSXT	386445
CSXT	386446
CSXT	386447
CSXT	386448
CSXT	386449

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	386450
CSXT	386451
CSXT	386452
CSXT	386453
CSXT	386454
CSXT	386455
CSXT	386456
CSXT	386457
CSXT	386458
CSXT	386459
CSXT	386460
CSXT	386461
CSXT	386462
CSXT	386463
CSXT	386464
CSXT	386465
CSXT	386466
CSXT	386467
CSXT	386491
CSXT	386492
CSXT	386493
CSXT	386495
CSXT	386496
CSXT	386497
CSXT	386498
CSXT	386499
CSXT	386500
CSXT	386504
CSXT	386505
CSXT	386507
CSXT	386508
CSXT	386511
CSXT	386512
CSXT	386513
CSXT	386514
CSXT	386516
CSXT	386517
CSXT	386518
CSXT	386519
CSXT	386520
CSXT	386521
CSXT	386522
CSXT	386524
CSXT	386525
CSXT	386527
CSXT	386528
CSXT	386529
CSXT	386530
CSXT	386532
CSXT	386533
CSXT	386534
CSXT	386535
CSXT	386536
CSXT	386538
CSXT	386539
CSXT	386540
CSXT	386541

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	386542
CSXT	386543
CSXT	386544
CSXT	386545
CSXT	386548
CSXT	386549
CSXT	386550
CSXT	386551
CSXT	386553
CSXT	386554
CSXT	386556
CSXT	386557
CSXT	386558
CSXT	386559
CSXT	386560
CSXT	387252
CSXT	387253
CSXT	387254
CSXT	387255
CSXT	387256
CSXT	387257
CSXT	387258
CSXT	387259
CSXT	387260
CSXT	387261
CSXT	387262
CSXT	387263
CSXT	387264
CSXT	387265
CSXT	387266
CSXT	387267
CSXT	387268
CSXT	387269
CSXT	387270
CSXT	387271
CSXT	387272
CSXT	387273
CSXT	387274
CSXT	387275
CSXT	387276
CSXT	387277
CSXT	387278
CSXT	387279
CSXT	387280
CSXT	387281
CSXT	387282
CSXT	387283
CSXT	387284
CSXT	387285
CSXT	387286
CSXT	387287
CSXT	387288
CSXT	387289
CSXT	387290
CSXT	387291
CSXT	387292
CSXT	387293

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387294
CSXT	387295
CSXT	387296
CSXT	387297
CSXT	387298
CSXT	387299
CSXT	387300
CSXT	387301
CSXT	387302
CSXT	387303
CSXT	387304
CSXT	387305
CSXT	387306
CSXT	387307
CSXT	387308
CSXT	387309
CSXT	387310
CSXT	387311
CSXT	387312
CSXT	387313
CSXT	387314
CSXT	387315
CSXT	387316
CSXT	387317
CSXT	387318
CSXT	387319
CSXT	387320
CSXT	387321
CSXT	387322
CSXT	387323
CSXT	387324
CSXT	387325
CSXT	387326
CSXT	387327
CSXT	387328
CSXT	387329
CSXT	387330
CSXT	387331
CSXT	387332
CSXT	387333
CSXT	387334
CSXT	387335
CSXT	387336
CSXT	387337
CSXT	387338
CSXT	387339
CSXT	387340
CSXT	387341
CSXT	387342
CSXT	387343
CSXT	387344
CSXT	387345
CSXT	387346
CSXT	387347
CSXT	387348
CSXT	387349
CSXT	387350

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387351
CSXT	387352
CSXT	387353
CSXT	387354
CSXT	387355
CSXT	387356
CSXT	387357
CSXT	387358
CSXT	387359
CSXT	387360
CSXT	387361
CSXT	387362
CSXT	387363
CSXT	387364
CSXT	387365
CSXT	387366
CSXT	387367
CSXT	387368
CSXT	387369
CSXT	387370
CSXT	387371
CSXT	387372
CSXT	387373
CSXT	387374
CSXT	387375
CSXT	387376
CSXT	387377
CSXT	387378
CSXT	387379
CSXT	387380
CSXT	387381
CSXT	387382
CSXT	387383
CSXT	387384
CSXT	387385
CSXT	387386
CSXT	387387
CSXT	387388
CSXT	387389
CSXT	387390
CSXT	387391
CSXT	387392
CSXT	387393
CSXT	387394
CSXT	387395
CSXT	387396
CSXT	387397
CSXT	387398
CSXT	387399
CSXT	387400
CSXT	387401
CSXT	387402
CSXT	387403
CSXT	387404
CSXT	387405
CSXT	387406
CSXT	387407

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387408
CSXT	387409
CSXT	387410
CSXT	387411
CSXT	387412
CSXT	387413
CSXT	387414
CSXT	387415
CSXT	387416
CSXT	387417
CSXT	387418
CSXT	387419
CSXT	387420
CSXT	387421
CSXT	387422
CSXT	387423
CSXT	387424
CSXT	387425
CSXT	387426
CSXT	387427
CSXT	387428
CSXT	387429
CSXT	387430
CSXT	387431
CSXT	387432
CSXT	387433
CSXT	387434
CSXT	387435
CSXT	387436
CSXT	387437
CSXT	387438
CSXT	387439
CSXT	387440
CSXT	387441
CSXT	387442
CSXT	387443
CSXT	387444
CSXT	387445
CSXT	387446
CSXT	387447
CSXT	387448
CSXT	387449
CSXT	387450
CSXT	387451
CSXT	387452
CSXT	387453
CSXT	387454
CSXT	387455
CSXT	387456
CSXT	387457
CSXT	387458
CSXT	387459
CSXT	387460
CSXT	387461
CSXT	387462
CSXT	387463
CSXT	387464

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387465
CSXT	387466
CSXT	387467
CSXT	387468
CSXT	387469
CSXT	387470
CSXT	387471
CSXT	387472
CSXT	387473
CSXT	387474
CSXT	387475
CSXT	387476
CSXT	387477
CSXT	387478
CSXT	387479
CSXT	387480
CSXT	387481
CSXT	387482
CSXT	387483
CSXT	387484
CSXT	387485
CSXT	387486
CSXT	387487
CSXT	387488
CSXT	387489
CSXT	387490
CSXT	387491
CSXT	387492
CSXT	387493
CSXT	387494
CSXT	387495
CSXT	387496
CSXT	387497
CSXT	387498
CSXT	387499
CSXT	387500
CSXT	387501
CSXT	387502
CSXT	387503
CSXT	387504
CSXT	387505
CSXT	387506
CSXT	387507
CSXT	387508
CSXT	387509
CSXT	387510
CSXT	387511
CSXT	387512
CSXT	387513
CSXT	387514
CSXT	387515
CSXT	387516
CSXT	387517
CSXT	387518
CSXT	387519
CSXT	387520
CSXT	387521

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387522
CSXT	387523
CSXT	387524
CSXT	387525
CSXT	387526
CSXT	387527
CSXT	387528
CSXT	387529
CSXT	387530
CSXT	387531
CSXT	387532
CSXT	387533
CSXT	387534
CSXT	387535
CSXT	387536
CSXT	387537
CSXT	387538
CSXT	387539
CSXT	387540
CSXT	387541
CSXT	387542
CSXT	387543
CSXT	387544
CSXT	387545
CSXT	387546
CSXT	387547
CSXT	387548
CSXT	387549
CSXT	387550
CSXT	387551
CSXT	387552
CSXT	387553
CSXT	387554
CSXT	387555
CSXT	387556
CSXT	387557
CSXT	387558
CSXT	387559
CSXT	387560
CSXT	387561
CSXT	387562
CSXT	387563
CSXT	387564
CSXT	387565
CSXT	387566
CSXT	387567
CSXT	387568
CSXT	387569
CSXT	387570
CSXT	387571
CSXT	387572
CSXT	387573
CSXT	387574
CSXT	387575
CSXT	387576
CSXT	387577
CSXT	387578

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	387579
CSXT	387580
CSXT	387581
CSXT	387582
CSXT	387583
CSXT	387584
CSXT	387585
CSXT	387586
CSXT	387587
CSXT	387588
CSXT	387589
CSXT	387590
CSXT	387591
CSXT	387592
CSXT	387593
CSXT	387594
CSXT	387595
CSXT	387596
CSXT	387597
CSXT	387598
CSXT	387599
CSXT	387600
CSXT	387601
CSXT	387602
CSXT	387603
CSXT	387604
CSXT	387605
CSXT	387606
CSXT	387607
CSXT	387608
CSXT	387609
CSXT	387610
CSXT	387611
CSXT	387612
CSXT	387613
CSXT	387614
CSXT	387615
CSXT	387616
CSXT	387617
CSXT	387618
CSXT	387619
CSXT	387620
CSXT	387621
CSXT	387622
CSXT	387623
CSXT	387624
CSXT	387625
CSXT	387626
CSXT	387627
CSXT	387628
CSXT	387629
CSXT	387630
CSXT	387631
CSXT	387632
CSXT	387633
CSXT	387634
CSXT	387635

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387636
CSXT	387637
CSXT	387638
CSXT	387639
CSXT	387640
CSXT	387641
CSXT	387642
CSXT	387643
CSXT	387644
CSXT	387645
CSXT	387646
CSXT	387647
CSXT	387648
CSXT	387649
CSXT	387650
CSXT	387651
CSXT	387652
CSXT	387653
CSXT	387654
CSXT	387655
CSXT	387656
CSXT	387657
CSXT	387658
CSXT	387659
CSXT	387660
CSXT	387661
CSXT	387662
CSXT	387663
CSXT	387664
CSXT	387665
CSXT	387666
CSXT	387667
CSXT	387668
CSXT	387669
CSXT	387670
CSXT	387671
CSXT	387672
CSXT	387673
CSXT	387674
CSXT	387675
CSXT	387676
CSXT	387677
CSXT	387678
CSXT	387679
CSXT	387680
CSXT	387681
CSXT	387682
CSXT	387683
CSXT	387684
CSXT	387685
CSXT	387686
CSXT	387687
CSXT	387688
CSXT	387689
CSXT	387690
CSXT	387691
CSXT	387692

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	387693
CSXT	387694
CSXT	387695
CSXT	387696
CSXT	387697
CSXT	387698
CSXT	387699
CSXT	387700
CSXT	387701
CSXT	387702
CSXT	387703
CSXT	387704
CSXT	387705
CSXT	387706
CSXT	387707
CSXT	387708
CSXT	387709
CSXT	387710
CSXT	387711
CSXT	387712
CSXT	387713
CSXT	387714
CSXT	387715
CSXT	387716
CSXT	387717
CSXT	387718
CSXT	387719
CSXT	387720
CSXT	387721
CSXT	387722
CSXT	387723
CSXT	387724
CSXT	387725
CSXT	387726
CSXT	387727
CSXT	387728
CSXT	387729
CSXT	387730
CSXT	387731
CSXT	387732
CSXT	387733
CSXT	387734
CSXT	387735
CSXT	387736
CSXT	387737
CSXT	387738
CSXT	387739
CSXT	387740
CSXT	387741
CSXT	387742
CSXT	387743
CSXT	387744
CSXT	387745
CSXT	387746
CSXT	387747
CSXT	387748
CSXT	387749

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	387750
CSXT	387751
CSXT	387752
CSXT	387753
CSXT	387754
CSXT	387755
CSXT	387756
CSXT	387757
CSXT	387758
CSXT	387759
CSXT	387760
CSXT	387761
CSXT	387762
CSXT	387763
CSXT	387764
CSXT	387765
CSXT	387766
CSXT	387767
CSXT	387768
CSXT	387769
CSXT	387770
CSXT	387771
CSXT	387772
CSXT	387773
CSXT	387774
CSXT	387775
CSXT	387776
CSXT	387777
CSXT	387778
CSXT	387779
CSXT	387780
CSXT	387781
CSXT	387782
CSXT	387783
CSXT	387784
CSXT	387785
CSXT	387786
CSXT	387787
CSXT	387788
CSXT	387789
CSXT	387790
CSXT	387791
CSXT	387792
CSXT	387793
CSXT	387794
CSXT	387795
CSXT	387796
CSXT	387797
CSXT	387798
CSXT	387799
CSXT	387800
CSXT	387801
CSXT	387802
CSXT	387803
CSXT	387804
CSXT	387805
CSXT	387806

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387807
CSXT	387808
CSXT	387809
CSXT	387810
CSXT	387811
CSXT	387812
CSXT	387813
CSXT	387814
CSXT	387815
CSXT	387816
CSXT	387817
CSXT	387818
CSXT	387819
CSXT	387820
CSXT	387821
CSXT	387822
CSXT	387823
CSXT	387824
CSXT	387825
CSXT	387826
CSXT	387827
CSXT	387828
CSXT	387829
CSXT	387830
CSXT	387831
CSXT	387832
CSXT	387833
CSXT	387834
CSXT	387835
CSXT	387836
CSXT	387837
CSXT	387838
CSXT	387839
CSXT	387840
CSXT	387841
CSXT	387842
CSXT	387843
CSXT	387844
CSXT	387845
CSXT	387846
CSXT	387847
CSXT	387848
CSXT	387849
CSXT	387850
CSXT	387851
CSXT	387852
CSXT	387853
CSXT	387854
CSXT	387855
CSXT	387856
CSXT	387857
CSXT	387858
CSXT	387859
CSXT	387860
CSXT	387861
CSXT	387862
CSXT	387863

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387864
CSXT	387865
CSXT	387866
CSXT	387867
CSXT	387868
CSXT	387869
CSXT	387870
CSXT	387871
CSXT	387872
CSXT	387873
CSXT	387874
CSXT	387875
CSXT	387876
CSXT	387877
CSXT	387878
CSXT	387879
CSXT	387880
CSXT	387881
CSXT	387882
CSXT	387883
CSXT	387884
CSXT	387885
CSXT	387886
CSXT	387887
CSXT	387888
CSXT	387889
CSXT	387890
CSXT	387891
CSXT	387892
CSXT	387893
CSXT	387894
CSXT	387895
CSXT	387896
CSXT	387897
CSXT	387898
CSXT	387899
CSXT	387900
CSXT	387901
CSXT	387902
CSXT	387903
CSXT	387904
CSXT	387905
CSXT	387906
CSXT	387907
CSXT	387908
CSXT	387909
CSXT	387910
CSXT	387911
CSXT	387912
CSXT	387913
CSXT	387914
CSXT	387915
CSXT	387916
CSXT	387917
CSXT	387918
CSXT	387919
CSXT	387920

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387921
CSXT	387922
CSXT	387923
CSXT	387924
CSXT	387925
CSXT	387926
CSXT	387927
CSXT	387928
CSXT	387929
CSXT	387930
CSXT	387931
CSXT	387932
CSXT	387933
CSXT	387934
CSXT	387935
CSXT	387936
CSXT	387937
CSXT	387938
CSXT	387939
CSXT	387940
CSXT	387941
CSXT	387942
CSXT	387943
CSXT	387944
CSXT	387945
CSXT	387946
CSXT	387947
CSXT	387948
CSXT	387949
CSXT	387950
CSXT	387951
CSXT	387952
CSXT	387953
CSXT	387954
CSXT	387955
CSXT	387956
CSXT	387957
CSXT	387958
CSXT	387959
CSXT	387960
CSXT	387961
CSXT	387962
CSXT	387963
CSXT	387964
CSXT	387965
CSXT	387966
CSXT	387967
CSXT	387968
CSXT	387969
CSXT	387970
CSXT	387971
CSXT	387972
CSXT	387973
CSXT	387974
CSXT	387975
CSXT	387976
CSXT	387977

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	387978
CSXT	387979
CSXT	387980
CSXT	387981
CSXT	387982
CSXT	387983
CSXT	387984
CSXT	387985
CSXT	387986
CSXT	387987
CSXT	387988
CSXT	387989
CSXT	387990
CSXT	387991
CSXT	387992
CSXT	387993
CSXT	387994
CSXT	387995
CSXT	387996
CSXT	387997
CSXT	387998
CSXT	387999
CSXT	388000
CSXT	388001
CSXT	388002
CSXT	388003
CSXT	388004
CSXT	388005
CSXT	388006
CSXT	388007
CSXT	388008
CSXT	388009
CSXT	388010
CSXT	388011
CSXT	388012
CSXT	388013
CSXT	388014
CSXT	388015
CSXT	388016
CSXT	388017
CSXT	388018
CSXT	388019
CSXT	388020
CSXT	388021
CSXT	388022
CSXT	388023
CSXT	388024
CSXT	388025
CSXT	388026
CSXT	388027
CSXT	388028
CSXT	388029
CSXT	388030
CSXT	388031
CSXT	388032
CSXT	388033
CSXT	388034

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388035
CSXT	388036
CSXT	388037
CSXT	388038
CSXT	388039
CSXT	388040
CSXT	388041
CSXT	388042
CSXT	388043
CSXT	388044
CSXT	388045
CSXT	388046
CSXT	388047
CSXT	388048
CSXT	388049
CSXT	388050
CSXT	388051
CSXT	388052
CSXT	388053
CSXT	388054
CSXT	388055
CSXT	388056
CSXT	388057
CSXT	388058
CSXT	388059
CSXT	388060
CSXT	388061
CSXT	388062
CSXT	388063
CSXT	388064
CSXT	388065
CSXT	388066
CSXT	388067
CSXT	388068
CSXT	388069
CSXT	388070
CSXT	388071
CSXT	388072
CSXT	388073
CSXT	388074
CSXT	388075
CSXT	388076
CSXT	388077
CSXT	388078
CSXT	388079
CSXT	388080
CSXT	388081
CSXT	388082
CSXT	388083
CSXT	388084
CSXT	388085
CSXT	388086
CSXT	388087
CSXT	388088
CSXT	388089
CSXT	388090
CSXT	388091

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388092
CSXT	388093
CSXT	388094
CSXT	388095
CSXT	388096
CSXT	388097
CSXT	388098
CSXT	388099
CSXT	388100
CSXT	388101
CSXT	388102
CSXT	388103
CSXT	388104
CSXT	388105
CSXT	388106
CSXT	388107
CSXT	388108
CSXT	388109
CSXT	388110
CSXT	388111
CSXT	388112
CSXT	388113
CSXT	388114
CSXT	388115
CSXT	388116
CSXT	388117
CSXT	388118
CSXT	388119
CSXT	388120
CSXT	388121
CSXT	388122
CSXT	388123
CSXT	388124
CSXT	388125
CSXT	388126
CSXT	388127
CSXT	388128
CSXT	388129
CSXT	388130
CSXT	388131
CSXT	388132
CSXT	388133
CSXT	388134
CSXT	388135
CSXT	388136
CSXT	388137
CSXT	388138
CSXT	388139
CSXT	388140
CSXT	388141
CSXT	388142
CSXT	388143
CSXT	388144
CSXT	388145
CSXT	388146
CSXT	388147
CSXT	388148

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388149
CSXT	388150
CSXT	388151
CSXT	388152
CSXT	388153
CSXT	388154
CSXT	388155
CSXT	388156
CSXT	388157
CSXT	388158
CSXT	388159
CSXT	388160
CSXT	388161
CSXT	388162
CSXT	388163
CSXT	388164
CSXT	388165
CSXT	388166
CSXT	388167
CSXT	388168
CSXT	388169
CSXT	388170
CSXT	388171
CSXT	388172
CSXT	388173
CSXT	388174
CSXT	388175
CSXT	388176
CSXT	388177
CSXT	388178
CSXT	388179
CSXT	388180
CSXT	388181
CSXT	388182
CSXT	388183
CSXT	388184
CSXT	388185
CSXT	388186
CSXT	388187
CSXT	388188
CSXT	388189
CSXT	388190
CSXT	388191
CSXT	388192
CSXT	388193
CSXT	388194
CSXT	388195
CSXT	388196
CSXT	388197
CSXT	388198
CSXT	388199
CSXT	388200
CSXT	388201
CSXT	388202
CSXT	388203
CSXT	388204
CSXT	388205

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388206
CSXT	388207
CSXT	388208
CSXT	388209
CSXT	388210
CSXT	388211
CSXT	388212
CSXT	388213
CSXT	388214
CSXT	388215
CSXT	388216
CSXT	388217
CSXT	388218
CSXT	388219
CSXT	388220
CSXT	388221
CSXT	388222
CSXT	388223
CSXT	388224
CSXT	388225
CSXT	388226
CSXT	388227
CSXT	388228
CSXT	388229
CSXT	388230
CSXT	388231
CSXT	388232
CSXT	388233
CSXT	388234
CSXT	388235
CSXT	388236
CSXT	388237
CSXT	388238
CSXT	388239
CSXT	388240
CSXT	388241
CSXT	388242
CSXT	388243
CSXT	388244
CSXT	388245
CSXT	388246
CSXT	388247
CSXT	388248
CSXT	388249
CSXT	388250
CSXT	388251
CSXT	388252
CSXT	388253
CSXT	388254
CSXT	388255
CSXT	388256
CSXT	388257
CSXT	388258
CSXT	388259
CSXT	388260
CSXT	388261
CSXT	388262

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388263
CSXT	388264
CSXT	388265
CSXT	388266
CSXT	388267
CSXT	388268
CSXT	388269
CSXT	388270
CSXT	388271
CSXT	388272
CSXT	388273
CSXT	388274
CSXT	388275
CSXT	388276
CSXT	388277
CSXT	388278
CSXT	388279
CSXT	388280
CSXT	388281
CSXT	388282
CSXT	388283
CSXT	388284
CSXT	388285
CSXT	388286
CSXT	388287
CSXT	388288
CSXT	388289
CSXT	388290
CSXT	388291
CSXT	388292
CSXT	388293
CSXT	388294
CSXT	388295
CSXT	388296
CSXT	388297
CSXT	388298
CSXT	388299
CSXT	388300
CSXT	388301
CSXT	388302
CSXT	388303
CSXT	388304
CSXT	388305
CSXT	388306
CSXT	388307
CSXT	388308
CSXT	388309
CSXT	388310
CSXT	388311
CSXT	388312
CSXT	388313
CSXT	388314
CSXT	388315
CSXT	388316
CSXT	388317
CSXT	388318
CSXT	388319

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388320
CSXT	388321
CSXT	388322
CSXT	388323
CSXT	388324
CSXT	388325
CSXT	388326
CSXT	388327
CSXT	388328
CSXT	388329
CSXT	388330
CSXT	388331
CSXT	388332
CSXT	388333
CSXT	388334
CSXT	388335
CSXT	388336
CSXT	388337
CSXT	388338
CSXT	388339
CSXT	388340
CSXT	388341
CSXT	388342
CSXT	388343
CSXT	388344
CSXT	388345
CSXT	388346
CSXT	388347
CSXT	388348
CSXT	388349
CSXT	388350
CSXT	388351
CSXT	388352
CSXT	388353
CSXT	388354
CSXT	388355
CSXT	388356
CSXT	388357
CSXT	388358
CSXT	388359
CSXT	388360
CSXT	388361
CSXT	388362
CSXT	388363
CSXT	388364
CSXT	388365
CSXT	388366
CSXT	388367
CSXT	388368
CSXT	388369
CSXT	388370
CSXT	388371
CSXT	388372
CSXT	388373
CSXT	388374
CSXT	388375
CSXT	388376

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388377
CSXT	388378
CSXT	388379
CSXT	388380
CSXT	388381
CSXT	388382
CSXT	388383
CSXT	388384
CSXT	388385
CSXT	388386
CSXT	388387
CSXT	388388
CSXT	388389
CSXT	388390
CSXT	388391
CSXT	388392
CSXT	388393
CSXT	388394
CSXT	388395
CSXT	388396
CSXT	388397
CSXT	388398
CSXT	388399
CSXT	388400
CSXT	388401
CSXT	388402
CSXT	388403
CSXT	388404
CSXT	388405
CSXT	388406
CSXT	388407
CSXT	388408
CSXT	388409
CSXT	388410
CSXT	388411
CSXT	388412
CSXT	388413
CSXT	388414
CSXT	388415
CSXT	388416
CSXT	388417
CSXT	388418
CSXT	388419
CSXT	388420
CSXT	388421
CSXT	388422
CSXT	388423
CSXT	388424
CSXT	388425
CSXT	388426
CSXT	388427
CSXT	388428
CSXT	388429
CSXT	388430
CSXT	388431
CSXT	388432
CSXT	388433

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388434
CSXT	388435
CSXT	388436
CSXT	388437
CSXT	388438
CSXT	388439
CSXT	388440
CSXT	388441
CSXT	388442
CSXT	388443
CSXT	388444
CSXT	388445
CSXT	388446
CSXT	388447
CSXT	388448
CSXT	388449
CSXT	388450
CSXT	388451
CSXT	388452
CSXT	388453
CSXT	388454
CSXT	388455
CSXT	388456
CSXT	388457
CSXT	388458
CSXT	388459
CSXT	388460
CSXT	388461
CSXT	388462
CSXT	388463
CSXT	388464
CSXT	388465
CSXT	388466
CSXT	388467
CSXT	388468
CSXT	388469
CSXT	388470
CSXT	388471
CSXT	388472
CSXT	388473
CSXT	388474
CSXT	388475
CSXT	388476
CSXT	388477
CSXT	388478
CSXT	388479
CSXT	388480
CSXT	388481
CSXT	388482
CSXT	388483
CSXT	388484
CSXT	388485
CSXT	388486
CSXT	388487
CSXT	388488
CSXT	388489
CSXT	388490

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388491
CSXT	388492
CSXT	388493
CSXT	388494
CSXT	388495
CSXT	388496
CSXT	388497
CSXT	388498
CSXT	388499
CSXT	388500
CSXT	388501
CSXT	388502
CSXT	388503
CSXT	388504
CSXT	388505
CSXT	388506
CSXT	388507
CSXT	388508
CSXT	388509
CSXT	388510
CSXT	388511
CSXT	388512
CSXT	388513
CSXT	388514
CSXT	388515
CSXT	388516
CSXT	388517
CSXT	388518
CSXT	388519
CSXT	388520
CSXT	388521
CSXT	388522
CSXT	388523
CSXT	388524
CSXT	388525
CSXT	388526
CSXT	388527
CSXT	388528
CSXT	388529
CSXT	388530
CSXT	388531
CSXT	388532
CSXT	388533
CSXT	388534
CSXT	388535
CSXT	388536
CSXT	388537
CSXT	388538
CSXT	388539
CSXT	388540
CSXT	388541
CSXT	388542
CSXT	388543
CSXT	388544
CSXT	388545
CSXT	388546
CSXT	388547

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388548
CSXT	388549
CSXT	388550
CSXT	388551
CSXT	388552
CSXT	388553
CSXT	388554
CSXT	388555
CSXT	388556
CSXT	388557
CSXT	388558
CSXT	388559
CSXT	388560
CSXT	388561
CSXT	388562
CSXT	388563
CSXT	388564
CSXT	388565
CSXT	388566
CSXT	388567
CSXT	388568
CSXT	388569
CSXT	388570
CSXT	388571
CSXT	388572
CSXT	388573
CSXT	388574
CSXT	388575
CSXT	388576
CSXT	388577
CSXT	388578
CSXT	388579
CSXT	388580
CSXT	388581
CSXT	388582
CSXT	388583
CSXT	388584
CSXT	388585
CSXT	388586
CSXT	388587
CSXT	388588
CSXT	388589
CSXT	388590
CSXT	388591
CSXT	388592
CSXT	388593
CSXT	388594
CSXT	388595
CSXT	388596
CSXT	388597
CSXT	388598
CSXT	388599
CSXT	388600
CSXT	388601
CSXT	388602
CSXT	388603
CSXT	388604

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388605
CSXT	388606
CSXT	388607
CSXT	388608
CSXT	388609
CSXT	388610
CSXT	388611
CSXT	388612
CSXT	388613
CSXT	388614
CSXT	388615
CSXT	388616
CSXT	388617
CSXT	388618
CSXT	388619
CSXT	388620
CSXT	388621
CSXT	388622
CSXT	388623
CSXT	388624
CSXT	388625
CSXT	388626
CSXT	388627
CSXT	388628
CSXT	388629
CSXT	388630
CSXT	388631
CSXT	388632
CSXT	388633
CSXT	388634
CSXT	388635
CSXT	388636
CSXT	388637
CSXT	388638
CSXT	388639
CSXT	388640
CSXT	388641
CSXT	388642
CSXT	388643
CSXT	388644
CSXT	388645
CSXT	388646
CSXT	388647
CSXT	388648
CSXT	388649
CSXT	388650
CSXT	388651
CSXT	388652
CSXT	388653
CSXT	388654
CSXT	388655
CSXT	388656
CSXT	388657
CSXT	388658
CSXT	388659
CSXT	388660
CSXT	388661

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388662
CSXT	388663
CSXT	388664
CSXT	388665
CSXT	388666
CSXT	388667
CSXT	388668
CSXT	388669
CSXT	388670
CSXT	388671
CSXT	388672
CSXT	388673
CSXT	388674
CSXT	388675
CSXT	388676
CSXT	388677
CSXT	388678
CSXT	388679
CSXT	388680
CSXT	388681
CSXT	388682
CSXT	388683
CSXT	388684
CSXT	388685
CSXT	388686
CSXT	388687
CSXT	388688
CSXT	388689
CSXT	388690
CSXT	388691
CSXT	388692
CSXT	388693
CSXT	388694
CSXT	388695
CSXT	388696
CSXT	388697
CSXT	388698
CSXT	388699
CSXT	388700
CSXT	388701
CSXT	388702
CSXT	388703
CSXT	388704
CSXT	388705
CSXT	388706
CSXT	388707
CSXT	388708
CSXT	388709
CSXT	388710
CSXT	388711
CSXT	388712
CSXT	388713
CSXT	388714
CSXT	388715
CSXT	388716
CSXT	388717
CSXT	388718

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388719
CSXT	388720
CSXT	388721
CSXT	388722
CSXT	388723
CSXT	388724
CSXT	388725
CSXT	388726
CSXT	388727
CSXT	388728
CSXT	388729
CSXT	388730
CSXT	388731
CSXT	388732
CSXT	388733
CSXT	388734
CSXT	388735
CSXT	388736
CSXT	388737
CSXT	388738
CSXT	388739
CSXT	388740
CSXT	388741
CSXT	388742
CSXT	388743
CSXT	388744
CSXT	388745
CSXT	388746
CSXT	388747
CSXT	388748
CSXT	388749
CSXT	388750
CSXT	388751
CSXT	388752
CSXT	388753
CSXT	388754
CSXT	388755
CSXT	388756
CSXT	388757
CSXT	388758
CSXT	388759
CSXT	388760
CSXT	388761
CSXT	388762
CSXT	388763
CSXT	388764
CSXT	388765
CSXT	388766
CSXT	388767
CSXT	388768
CSXT	388769
CSXT	388770
CSXT	388771
CSXT	388772
CSXT	388773
CSXT	388774
CSXT	388775

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388776
CSXT	388777
CSXT	388778
CSXT	388779
CSXT	388780
CSXT	388781
CSXT	388782
CSXT	388783
CSXT	388784
CSXT	388785
CSXT	388786
CSXT	388787
CSXT	388788
CSXT	388789
CSXT	388790
CSXT	388791
CSXT	388792
CSXT	388793
CSXT	388794
CSXT	388795
CSXT	388796
CSXT	388797
CSXT	388798
CSXT	388799
CSXT	388800
CSXT	388801
CSXT	388802
CSXT	388803
CSXT	388804
CSXT	388805
CSXT	388806
CSXT	388807
CSXT	388808
CSXT	388809
CSXT	388810
CSXT	388811
CSXT	388812
CSXT	388813
CSXT	388814
CSXT	388815
CSXT	388816
CSXT	388817
CSXT	388818
CSXT	388819
CSXT	388820
CSXT	388821
CSXT	388822
CSXT	388823
CSXT	388824
CSXT	388825
CSXT	388826
CSXT	388827
CSXT	388828
CSXT	388829
CSXT	388830
CSXT	388831
CSXT	388832

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	388833
CSXT	388834
CSXT	388835
CSXT	388836
CSXT	388837
CSXT	388838
CSXT	388839
CSXT	388840
CSXT	388841
CSXT	388842
CSXT	388843
CSXT	388844
CSXT	388845
CSXT	388846
CSXT	388847
CSXT	388848
CSXT	388849
CSXT	388850
CSXT	388851
CSXT	388852
CSXT	388853
CSXT	388854
CSXT	388855
CSXT	388856
CSXT	388857
CSXT	388858
CSXT	388859
CSXT	388860
CSXT	388861
CSXT	388862
CSXT	388863
CSXT	388864
CSXT	388865
CSXT	388866
CSXT	388867
CSXT	388868
CSXT	388869
CSXT	388870
CSXT	388871
CSXT	388872
CSXT	388873
CSXT	388874
CSXT	388875
CSXT	388876
CSXT	388877
CSXT	388878
CSXT	388879
CSXT	388880
CSXT	388881
CSXT	388882
CSXT	388883
CSXT	388884
CSXT	388885
CSXT	388886
CSXT	388887
CSXT	388888
CSXT	388889

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388890
CSXT	388891
CSXT	388892
CSXT	388893
CSXT	388894
CSXT	388895
CSXT	388896
CSXT	388897
CSXT	388898
CSXT	388899
CSXT	388900
CSXT	388901
CSXT	388902
CSXT	388903
CSXT	388904
CSXT	388905
CSXT	388906
CSXT	388907
CSXT	388908
CSXT	388909
CSXT	388910
CSXT	388911
CSXT	388912
CSXT	388913
CSXT	388914
CSXT	388915
CSXT	388916
CSXT	388917
CSXT	388918
CSXT	388919
CSXT	388920
CSXT	388921
CSXT	388922
CSXT	388923
CSXT	388924
CSXT	388925
CSXT	388926
CSXT	388927
CSXT	388928
CSXT	388929
CSXT	388930
CSXT	388931
CSXT	388932
CSXT	388933
CSXT	388934
CSXT	388935
CSXT	388936
CSXT	388937
CSXT	388938
CSXT	388939
CSXT	388940
CSXT	388941
CSXT	388942
CSXT	388943
CSXT	388944
CSXT	388945
CSXT	388946

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	388947
CSXT	388948
CSXT	388949
CSXT	388950
CSXT	388951
CSXT	388952
CSXT	388953
CSXT	388954
CSXT	388955
CSXT	388956
CSXT	388957
CSXT	388958
CSXT	388959
CSXT	388960
CSXT	388961
CSXT	388962
CSXT	388963
CSXT	388964
CSXT	388965
CSXT	388966
CSXT	388967
CSXT	388968
CSXT	388969
CSXT	388970
CSXT	388971
CSXT	388972
CSXT	388973
CSXT	388974
CSXT	388975
CSXT	388976
CSXT	388977
CSXT	388978
CSXT	388979
CSXT	388980
CSXT	388981
CSXT	388982
CSXT	388983
CSXT	388984
CSXT	388985
CSXT	388986
CSXT	388987
CSXT	388988
CSXT	388989
CSXT	388990
CSXT	388991
CSXT	388992
CSXT	388993
CSXT	388994
CSXT	388995
CSXT	388996
CSXT	388997
CSXT	388998
CSXT	388999
CSXT	389000
CSXT	389001
CSXT	389002
CSXT	389003

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389004
CSXT	389005
CSXT	389006
CSXT	389007
CSXT	389008
CSXT	389009
CSXT	389010
CSXT	389011
CSXT	389012
CSXT	389013
CSXT	389014
CSXT	389015
CSXT	389016
CSXT	389017
CSXT	389018
CSXT	389019
CSXT	389020
CSXT	389021
CSXT	389022
CSXT	389023
CSXT	389024
CSXT	389025
CSXT	389026
CSXT	389027
CSXT	389028
CSXT	389029
CSXT	389030
CSXT	389031
CSXT	389032
CSXT	389033
CSXT	389034
CSXT	389035
CSXT	389036
CSXT	389037
CSXT	389038
CSXT	389039
CSXT	389040
CSXT	389041
CSXT	389042
CSXT	389043
CSXT	389044
CSXT	389045
CSXT	389046
CSXT	389047
CSXT	389048
CSXT	389049
CSXT	389050
CSXT	389051
CSXT	389052
CSXT	389053
CSXT	389054
CSXT	389055
CSXT	389056
CSXT	389057
CSXT	389058
CSXT	389059
CSXT	389060

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

<u>NEW</u> <u>INITIAL</u>	<u>NEW</u> <u>NUMBER</u>
CSXT	389061
CSXT	389062
CSXT	389063
CSXT	389064
CSXT	389065
CSXT	389066
CSXT	389067
CSXT	389068
CSXT	389069
CSXT	389070
CSXT	389071
CSXT	389072
CSXT	389073
CSXT	389074
CSXT	389075
CSXT	389076
CSXT	389077
CSXT	389078
CSXT	389079
CSXT	389080
CSXT	389081
CSXT	389082
CSXT	389083
CSXT	389084
CSXT	389085
CSXT	389086
CSXT	389087
CSXT	389088
CSXT	389089
CSXT	389090
CSXT	389091
CSXT	389092
CSXT	389093
CSXT	389094
CSXT	389095
CSXT	389096
CSXT	389097
CSXT	389098
CSXT	389099
CSXT	389100
CSXT	389101
CSXT	389102
CSXT	389103
CSXT	389104
CSXT	389105
CSXT	389106
CSXT	389107
CSXT	389108
CSXT	389109
CSXT	389110
CSXT	389111
CSXT	389112
CSXT	389113
CSXT	389114
CSXT	389115
CSXT	389116
CSXT	389117

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389118
CSXT	389119
CSXT	389120
CSXT	389121
CSXT	389122
CSXT	389123
CSXT	389124
CSXT	389125
CSXT	389126
CSXT	389127
CSXT	389128
CSXT	389129
CSXT	389130
CSXT	389131
CSXT	389132
CSXT	389133
CSXT	389134
CSXT	389135
CSXT	389136
CSXT	389137
CSXT	389138
CSXT	389139
CSXT	389140
CSXT	389141
CSXT	389142
CSXT	389143
CSXT	389144
CSXT	389145
CSXT	389146
CSXT	389147
CSXT	389148
CSXT	389149
CSXT	389150
CSXT	389151
CSXT	389152
CSXT	389153
CSXT	389154
CSXT	389155
CSXT	389156
CSXT	389157
CSXT	389158
CSXT	389159
CSXT	389160
CSXT	389161
CSXT	389162
CSXT	389163
CSXT	389164
CSXT	389165
CSXT	389166
CSXT	389167
CSXT	389168
CSXT	389169
CSXT	389170
CSXT	389171
CSXT	389172
CSXT	389173
CSXT	389174

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389175
CSXT	389176
CSXT	389177
CSXT	389178
CSXT	389179
CSXT	389180
CSXT	389181
CSXT	389182
CSXT	389183
CSXT	389184
CSXT	389185
CSXT	389186
CSXT	389187
CSXT	389188
CSXT	389189
CSXT	389190
CSXT	389191
CSXT	389192
CSXT	389193
CSXT	389194
CSXT	389195
CSXT	389196
CSXT	389197
CSXT	389198
CSXT	389199
CSXT	389200
CSXT	389201
CSXT	389202
CSXT	389203
CSXT	389204
CSXT	389205
CSXT	389206
CSXT	389207
CSXT	389208
CSXT	389209
CSXT	389210
CSXT	389211
CSXT	389212
CSXT	389213
CSXT	389214
CSXT	389215
CSXT	389216
CSXT	389217
CSXT	389218
CSXT	389219
CSXT	389220
CSXT	389221
CSXT	389222
CSXT	389223
CSXT	389224
CSXT	389225
CSXT	389226
CSXT	389227
CSXT	389228
CSXT	389229
CSXT	389230
CSXT	389231

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389289
CSXT	389290
CSXT	389291
CSXT	389292
CSXT	389293
CSXT	389294
CSXT	389295
CSXT	389296
CSXT	389297
CSXT	389298
CSXT	389299
CSXT	389300
CSXT	389301
CSXT	389302
CSXT	389303
CSXT	389304
CSXT	389305
CSXT	389306
CSXT	389307
CSXT	389308
CSXT	389309
CSXT	389310
CSXT	389311
CSXT	389312
CSXT	389313
CSXT	389314
CSXT	389315
CSXT	389316
CSXT	389317
CSXT	389318
CSXT	389319
CSXT	389320
CSXT	389321
CSXT	389322
CSXT	389323
CSXT	389324
CSXT	389325
CSXT	389326
CSXT	389327
CSXT	389328
CSXT	389329
CSXT	389330
CSXT	389331
CSXT	389332
CSXT	389333
CSXT	389334
CSXT	389335
CSXT	389336
CSXT	389337
CSXT	389338
CSXT	389339
CSXT	389340
CSXT	389341
CSXT	389342
CSXT	389343
CSXT	389344
CSXT	389345

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389346
CSXT	389347
CSXT	389348
CSXT	389349
CSXT	389350
CSXT	389351
CSXT	389352
CSXT	389353
CSXT	389354
CSXT	389355
CSXT	389356
CSXT	389357
CSXT	389358
CSXT	389359
CSXT	389360
CSXT	389361
CSXT	389362
CSXT	389363
CSXT	389364
CSXT	389365
CSXT	389366
CSXT	389367
CSXT	389368
CSXT	389369
CSXT	389370
CSXT	389371
CSXT	389372
CSXT	389373
CSXT	389374
CSXT	389375
CSXT	389376
CSXT	389377
CSXT	389378
CSXT	389379
CSXT	389380
CSXT	389381
CSXT	389382
CSXT	389383
CSXT	389384
CSXT	389385
CSXT	389386
CSXT	389387
CSXT	389388
CSXT	389389
CSXT	389390
CSXT	389391
CSXT	389392
CSXT	389393
CSXT	389394
CSXT	389395
CSXT	389396
CSXT	389397
CSXT	389398
CSXT	389399
CSXT	389400
CSXT	389401
CSXT	389402

BATH TUB GONS IN 1991 FINANCED REPAIR PROGRAM

NEW INITIAL	NEW NUMBER
CSXT	389403
CSXT	389404
CSXT	389405
CSXT	389406
CSXT	389407
CSXT	389408
CSXT	389409
CSXT	389410
CSXT	389411
CSXT	389412
CSXT	389413
CSXT	389414
CSXT	389415
CSXT	389416
CSXT	389417
CSXT	389418
CSXT	389419
CSXT	389420
CSXT	389421
CSXT	389422
CSXT	389423
CSXT	389424
CSXT	389425
CSXT	389426
CSXT	389427
CSXT	389428
CSXT	389429
CSXT	389430
CSXT	389431
CSXT	389432
CSXT	389433
CSXT	389434
CSXT	389435
CSXT	389437
CSXT	389438
CSXT	389439
CSXT	389440

3400

SCHEDULE 2  
to  
Lease and Indenture  
Supplement No. 1

BASIC RENT

<u>Payment Date</u>		<u>Percentage of Lessor's Cost</u>
3/ 1/1992	0	2.26135556
9/ 1/1992	1	3.36400000
3/ 1/1993	2	6.17643759
9/ 1/1993	3	3.24573700
3/ 1/1994	4	6.29945536
9/ 1/1994	5	3.11732814
3/ 1/1995	6	6.42603197
9/ 1/1995	7	2.97819715
3/ 1/1996	8	6.56317834
9/ 1/1996	9	2.82744869
3/ 1/1997	10	6.71177581
9/ 1/1997	11	2.66411273
3/ 1/1998	12	6.87278065
9/ 1/1998	13	2.48713825
3/ 1/1999	14	7.04722973
9/ 1/1999	15	3.21165483
3/ 1/2000	16	8.32534659
9/ 1/2000	17	2.94499466
3/ 1/2001	18	8.69684833
9/ 1/2001	19	1.88218691
3/ 1/2002	20	9.75965608
9/ 1/2002	21	1.55115986
3/ 1/2003	22	10.09068313
9/ 1/2003	23	1.19249205
3/ 1/2004	24	10.44935093
9/ 1/2004	25	0.80387549
3/ 1/2005	26	10.83796750
9/ 1/2005	27	0.38280942
3/ 1/2006	28	11.25903357
9/ 1/2006	29	0.00000000
3/ 1/2007	30	11.64184299

SCHEDULE 3  
to  
Lease and Indenture  
Supplement No. 1

STIPULATED LOSS VALUE

If the event giving rise to an obligations to pay Stipulated Loss Value occurs and the actual date as of which the Owner Participant shall incur Federal income tax consequences shall be earlier or later than the date assumed in originally calculating the applicable Stipulated Loss Value, such value shall be appropriately adjusted, based upon the date as of which the Owner Participant incurred such tax consequences but otherwise on the same assumptions used to calculate the following values. In any case where Stipulated Loss Value shall be payable, there shall be added to the amount determined pursuant to the following schedule, the amount of premium, if any, payable in respect of the Certificates.

Notwithstanding any provision in the Lease to the contrary, the parties hereto acknowledge and agree that the following table of Stipulated Loss Value percentages has been calculated without regard to payment of Basic Rent as of the applicable Payment Date. Accordingly, the Lessee shall also pay the Basic Rent with respect to such Unit due on the applicable Payment Date.

The Stipulated Loss Value set forth in this Schedule 3 shall be applicable in respect of the Units leased hereunder on the date hereof.

<u>Payment Date</u>	<u>Percentage of Lessor's Cost</u>	<u>Payment Date</u>	<u>Percentage of Lessor's Cost</u>
1 MAR 1992	102.30135588	1 SEP 1999	81.46607597
1 SEP 1992	103.55504208	1 MAR 2000	75.45667461
1 MAR 1993	101.74574167	1 SEP 2000	74.63317524
1 SEP 1993	102.53876801	1 MAR 2001	68.08223522
1 MAR 1994	100.11621686	1 SEP 2001	68.11497321
1 SEP 1994	100.61185407	1 MAR 2002	60.37031647
1 MAR 1995	97.69449779	1 SEP 2002	60.62721142
1 SEP 1995	98.00250834	1 MAR 2003	52.47589407
1 MAR 1996	94.66504301	1 SEP 2003	53.01355066
1 SEP 1996	94.84746622	1 MAR 2004	44.45135453
1 MAR 1997	91.08212930	1 SEP 2004	45.32314795
1 SEP 1997	91.13333013	1 MAR 2005	36.34738067
1 MAR 1998	86.92495109	1 SEP 2005	37.61460663
1 SEP 1998	86.92495109	1 MAR 2006	28.22600961
1 MAR 1999	82.36485960	1 SEP 2006	29.80923383
		1 MAR 2007	20.00000000

SCHEDULE 4  
to  
Lease and Indenture  
Supplement No. 1

TERMINATION VALUE

If the event giving rise to an obligations to pay Termination Value occurs and the actual date as of which the Owner Participant shall incur Federal income tax consequences shall be earlier or later than the date assumed in originally calculating the applicable Termination Value, such value shall be appropriately adjusted, based upon the date as of which the Owner Participant incurred such tax consequences but otherwise on the same assumptions used to calculate the following values. In any case where Termination Value shall be payable, there shall be added to the amount determined pursuant to the following schedule, the amount of premium, if any, payable in respect of the Certificates.

Notwithstanding any provision in the Lease to the contrary, the parties hereto acknowledge and agree that the following table of Termination Value percentages has been calculated without regard to payment of Basic Rent as of the applicable Payment Date. Accordingly, the Lessee shall also pay the Basic Rent with respect to such Unit due on the applicable Payment Date.

The Termination Value set forth in this Schedule 4 shall be applicable in respect of the Units leased hereunder on the date hereof.

<u>Payment Date</u>	<u>Percentage of Lessor's Cost</u>	<u>Payment Date</u>	<u>Percentage of Lessor's Cost</u>
1 MAR 1992	102.30135588	1 SEP 1999	81.46607597
1 SEP 1992	103.55504208	1 MAR 2000	75.45667461
1 MAR 1993	101.74574167	1 SEP 2000	74.63317524
1 SEP 1993	102.53876801	1 MAR 2001	68.08223522
1 MAR 1994	100.11621686	1 SEP 2001	68.11497321
1 SEP 1994	100.61185407	1 MAR 2002	60.37031647
1 MAR 1995	97.69449779	1 SEP 2002	60.62721142
1 SEP 1995	98.00250834	1 MAR 2003	52.47589407
1 MAR 1996	94.66504301	1 SEP 2003	53.01355066
1 SEP 1996	94.84746622	1 MAR 2004	44.45135453
1 MAR 1997	91.08212930	1 SEP 2004	45.32314795
1 SEP 1997	91.13333013	1 MAR 2005	36.34738067
1 MAR 1998	86.92495109	1 SEP 2005	37.61460663
1 SEP 1998	86.92495109	1 MAR 2006	28.22600961
1 MAR 1999	82.36485960	1 SEP 2006	29.80923383
		1 MAR 2007	20.00000000